

BERMAZ ATLASBX BATTERY WARRANTY CONDITIONS

- This warranty applies **only to ATLASBX batteries purchased from Bermaz Authorized Dealers in Malaysia.**
- The warranty covers service by **Bermaz Authorized Automotive Battery Dealers only.**
- This warranty card **must be presented together with the original purchase receipt** when warranty service is required.
- This warranty card is **irreplaceable** in the event of loss.
- This warranty is **valid only in Malaysia.**
- Usage Classification:
 - Normal user – based on 5,000km driven every 8 weeks
 - Heavy user – based on 5,000km driven every 3 weeks

WARRANTY PERIOD: (FROM DATE OF PURCHASE)

- For petrol / diesel driven vehicle: 24 months or 50,000KM (whichever comes first)

WARRANTY FOR REPLACEMENT BATTERY

- The warranty period of the replacement battery will be computed as the warranty period of the original battery purchased, less the consumed service life of the original battery.
- Battery replacement shall not exceed more than one unit during the warranty period.

WARRANTY LIMITATIONS / EXCLUSIONS:

- This warranty, however, does not cover:
 - (a) Damage due to negligence / abuse / mishandling / accidents / explosions / jumpstart / fire / floods / acts of nature / overcharging / undercharging due to faulty charging, alternator of electrical system of the said vehicles / shorting from external source / cracking on battery casing due to dropping or knocking.
 - (b) Prolonged battery storage resulting in battery failure. (Above 6 months).

- (c) Any incidental or consequential damages arising from failure of battery.
- (d) Battery of lower capacity and / or smaller size is used, than recommended by the manufacturer, will void the warranty.
- (e) The battery has been altered, modified or misused other than its original design and purpose.
- (f) The battery has been transferred to another vehicle.
- (g) The battery has been tampered within any manner or misused.
- (h) Malfunctioning of your car's recharging and electrical system.
- (i) The battery casing breakage due to above reasons.
- (j) The battery Serial Number sticker is damaged.